




U.I. Lapp GmbH
Schulze Delitzsch Straße 25 D 70565 Stuttgart
www.lappgroup.com

Anbausteckverbinder, gerade

EPIC® LS1.5 A1 3+PE+2
EPIC® LS1.5 A1 3+PE+4



NICHT UNTER LAST STECKEN ODER TRENNEN
NOT FOR CURRENT INTERRUPTION
NE PAS UTILISER POUR COUPER LE COURANT

- Litzen an Kontakte crimpsen und durch den Haltering Pos. 1 schieben.
- Kontakte seitlich in Isolerkörper-Unterteil Pos. 2 einclippen.
- Isolerkörper-Unterteil Pos. 2 mit konfektionierten Kontakten in die Isolierhülse Pos. 3 schieben.
- Einheit Pos. 2 und Pos. 3 in das Gehäuse Pos. 4 einführen.
- Haltering Pos. 1 in das Gehäuse Pos. 4 montieren.
- Flanschsteckereinheit mit Schrauben Pos. 5 an der Montagewand befestigen.




U.I. Lapp GmbH
Schulze-Delitzsch-Straße 25 D-70565 Stuttgart
www.lappgroup.com

Panel base connectors, straight

EPIC® LS1.5 A1 3+PE+2

EPIC® LS1.5 A1 3+PE+4



- Crimp the conductors to the contacts and push them through the support (1).
- Clip the contacts into the lower part of the insulating body (2).
- Slice the lower part of the insulating body (2) with the assembled contacts into the insulating sleeve (3).
- Guide the unit (2) and (3) into the housing (4).
- Mount the support (1) in the housing (4).
- Secure flange connector unit to the mounting panel using screws (5).