









 8 640 67B 8 631 41B 8 633 41B 8 634 41B, 8 635 41B	 $-10^{\circ}\text{C} \dots +70^{\circ}\text{C}$  $-5^{\circ}\text{C} \dots +40^{\circ}\text{C}$ P $< 1 \text{ W}$ U, f $230 \text{ V} \sim$ $50 / 60 \text{ Hz}$	 $10^{\circ}\text{C} \dots 30^{\circ}\text{C}$ $\Delta K = \pm 2\text{K}$	 $250 \text{ V} \sim$ $8 \text{ A}, \cos \varphi = 1$ $2 \text{ A}, \cos \varphi = 0,6$	 6 mm  $1,5 \dots 4 \text{ mm}^2$ $1,5 \dots 2,5 \text{ mm}^2$
--	---	--	---	---





			ΔK	
-10°C ... +70°C	-5°C ... +40°C	1 ... 6 (10°C...60°C)	$\pm 2K$	

			P	U
$\leq 20\text{ m}$	250 V~ 16 A, $\cos \varphi = 1$	6 mm 1,5..4 mm ² 1,5..2,5 mm ²	< 1 W	230 V~ 50 / 60 Hz

4 m

8 631 42B
8 633 42B
8 634 42B
8 635 42B

④

③

⑤

②

⑥

①

Load

Temperature sensor

